

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

Applicant No. 10/607,737

Amended dated Nov. 19, 2003

Reply to Notice of Preliminary Action dated Sep. 23, 2003

### ABSTRACT

A protection relay for a power line system that employs current transformers for detecting current on a bus is provided with a fault trip scheme that includes transformer current saturation detection so as to avoid false tripping due to temporary transformer current saturation.